

5/10/23

QUICK PIK 1
2541020

Metal finishing



--	--	--	--

Provide sufficient ventilation.

If trained in accordance 29 CFR 1910.120, leaks should be stopped. Spills should be contained and cleaned immediately. Persons performing clean up work should wear adequate personal protective equipment and clothing. Spills and releases should be reported, if required, to the appropriate local, state and federal regulatory agencies.

Wear rubber gloves, goggles and chemical protective clothing.

Do not get in eyes, or on skin, or on clothing.

Avoid breathing dust, fumes, gas, mist, vapors and sprays.

Wash hands thoroughly after handling.

Store in cool dry place.

