Better Chemistry.

Revised: 10/20/15

1   IDENTIFICATION

ENE SOLDERING FLUX XX

2840004

Industrial applications

Hubbard-Hall Inc.

Telephone
Fax number:

CHEMTREC:
International:

2   HAZARDS IDENTIFICATION

3 COMPOSITION INFORMATION

Zinc Chloride	-	7446-85-7	~40%
Ammonium Chloride	Ammonium Muriate	12125-02-9	~10%

4 FIRST AID

Remove exposed person to fresh air and support breathing as needed.

Immediately remove contaminated clothing under a safety shower. Flush all affected areas with large amounts of water for 15 minutes. DO NOT attempt to neutralize with chemical agents. Obtain medical advice.

Immediately flush with plenty of water for at least 15 minutes. Remove contact lenses, if present and easy to do so. Continue rinsing. Call a physician or poison control center immediately.

Call a physician or poison control center immediately. Do not induce vomiting. Immediately rinse mouth and drink plenty of water. If vomiting occurs, keep head low so that the stomach content doesn't get into the lungs. Never give anything by mouth to an unconscious person. Do not use mouth-to-mouth method if victim ingested the substance.

5   FIRE FIGHTING MEASURES

Will not burn or support combustion. Use extinguishing media appropriate for surrounding fire, such as water spray, dry chemical, foam or carbon dioxide.

Fire fighters should enter area only if they are protected from all contact with the materail. Full protective clothing, including self-contained breathing apparatus, coat, pants, gloves, boots and bands around legs, arms, and waist, should be worn. No skin surfaces should be exposed.

6   ACCIDENTAL RELEASE MEASURES

Wear chemical goggle, gloves and face shield and protective clothing.

1840

ZINC CHLORIDE SOLUTION,

8

III

154

15 REGULATORY INFORMATION

Ammonium Chloride-RQ=5000 lbs
Zinc Chloride-1000 lbs-RQ

16 OTHER INFORMATION

The information is based on our knowledge to date but does not constitute an assurance of product properties and does not imply a legal contractual relationship.