Revised: 1/6/15

1 IDENTIFICATION

2343021

Industrial applications

Hubbard-Hall Inc.

Telephone Fax number:

CHEMTREC: International:

2

3 COMPOSITION INFORMATION

Phosphoric Acid		7664-38-2	<26%
Fluoboric Acid	-	66872-11-0	Approx 15%

4 FIRST AID

Remove exposed person to fresh air and support breathing as needed.

Immediately remove contaminated clothing under a safety shower. Flush all affected areas with large amounts of water for 15 minutes. DO NOT attempt to neutralize with chemical agents. Obtain medical advice.

Immediately flush with plenty of water for at least 15 minutes. Remove contact lenses, if present and easy to do so. Continue rinsing. Call a physician or poison control center immediately.

Call a physician or poison control center immediately. Do not induce vomiting. Immediately rinse mouth and drink plenty of water. If vomiting occurs, keep head low so that the stomach content doesn't get into the lungs. Never give anything by mouth to an unconscious person. Do not use mouth-to-mouth method if victim ingested the substance.

Symptons may include irriitation to the nose, throat and upper respiratory tract.

Adverse symptons may include the following: Symptons may include redness, pain, blurred vision, eye burns and permanent eye damage.

Adverse symptons may include the following: May cause redness, pain and severe skin burns.

Adverse symptons may include the following: Symptons may include severe burns of the mouth, throat and stomach. Ingestion of large quantities may cause gastrointestinal irritation, vomiting and diarrhea.

5 FIRE FIGHTING MEASURES

Will not burn or support combustion. Use extinguishing media appropriate for surrounding fire, such as water spray, dry chemical, foam or carbon dioxide.

Fire fighters should enter area only if they are protected from all contact with the materail. Full protective clothing, including self-contained breathing apparatus, coat, pants, gloves, boots and bands around legs, arms, and waist, should be worn. No skin surfaces should be exposed.

6 ACCIDENTAL RELEASE MEASURES

Wear chemical goggle, gloves and face shield and protective clothing.

Prevent spilled product from drains, sewers, waterways and soil.

Absorb the chemical onto sand, vermiculite, or any other non-combustible absorbent, and collect into containers for later disposal.

7 HANDLING AND STORAGE

Avoid breathing dust, fumes, gas, mist, vapors and sprays.

Wash hands thoroughly after handling.

Do not get in eyes, or on skin, or on clothing.

2343021 LASER® LL

10 STABILITY AND REACTIVITY

16 OTHER INFORMATION

The information is based on our knowledge to date but does not constitute an assurance of product properties and does not imply a legal contractual relationship.